

# RAILROAD INSPECTION REPORT

RAILROAD TPWRR

District #5

RR MILEPOST:

63.13

COUNTY: Mclean

ROUTE: FAS 294

LOCATION: Chenoa, IL

DOT/AAR: 802009C

DOT/AAR: 802009C



## TRACK TYPE

- ☒ Mainline  
☐ Passing  
☐ Siding  
☐ Interconnect  
☐ Abandoned

## BIT SURFACE

- High ☐ Low ☐  
Cracks ☐ Holes ☒  
Bit Surf Condition  
GOOD

## RAILS

- Rail Weight 131  
Rail Type CONV  
Rail loose? ☐  
Rail high? ☐  
Rail low? ☐

## CROSSING SURFACE

- Surface Type Concrete Pan  
Xing Length (feet) 57  
Ext Type  
Ext Length (feet) 0  
Number of Tracks 1  
Install Date 2016  
Median width: 0  
Rideability: Good

## PLANKS / PANELS

- OK ☒ Loose ☐  
Low ☐ Missing ☐  
Worn ☐ Rotted ☐

## APPROACH TIES

- FAIR  
☐ Good  
☐ Fair  
☐ Poor

Photo Dir. East Photo Date 5/16/2016

Overall Condition  
(Crossing)

SATISFACTORY

Recommendation

Needs Normal Maintenance

\*Railroad notified

- ☐ Satisfactory  
☐ Rough  
☐ Hazardous

- ☐ Needs Normal Maintenance  
☐ Needs Immediate Repairs\*

Comments  
(Track)

New concrete crossing with asphalt sub-base in 2016

## HIGHWAY APPROACHES

- Road appr dir 1 (N or E) NORTH  
Road appr wd 1 (feet) 24  
Road surf 1 BITUMINOUS  
Road Cond 1 FAIR  
Road appr dir 2 (S or W) SOUTH  
Road appr wd 2 (feet) 24  
Road surf 2 BITUMINOUS  
Road cond 2 FAIR

## BITUMINOUS TAPERS

- Rundown Dir 1 (N or E)  
Rundown Dir 2 (S or W)  
Rundown Length 1  
Rundown Length 2  
Rundown Cond 1  
Rundown Cond 2

Comments (Hwy)

Pavement on south side of crossing showing signs of severe rutting and cracking along edge of crossing surface.

State Inspector Derek Bridges, Kevin Knoepfel

Railroad Rep Alfonso Lopez, Don Taylor

Inspection Date 05/16/2016